Manufacturer Identification Report

1.	Manufacturer Equipment Service Address 4415 Douglas Road	Co., Inc.
2.	City Millstadt. Incorporated in the state of Illinois	State <u>II</u> Zip <u>62260-27</u> 19



A.TYPE OF B. TYPE OF							3. DESCRIPTION OF MOTOR VEHICLES MANUFACTURED C. TYPE OF						
VEHIC			OPERATOR					SSIS					
MPV TRUCK BUS	TRAILER	INC VEHICLE MFG	INTERMEDIATE MFG	FINAL-STAGE MFG	ALTERED-MFG	CHASSIS-CAB	CHASSIS-COWL	BARE CHASSIS	CUTAWAYCHASSIS	D. BODY STYLE	E. GVW RANGE F. OPERATIO	N PERFORMED	
X X X X			X X X X	X X X X	7	X X X X				Van Bodies Utility Bodies Dump Bodies Grain/Farm Bodie Cranes	lbs. to more than final stag 33,000 lbs. ing van bo s bodies, se grain/farm	dies, dump rvice bodie bodies,	
See reverse sic											cranes and acsessories cabs with (8,500 lbs. 33,000 lbs.	s on chassi GVWRs from to more th	

National Highway Traffic Safety Administration 400 7th St SW, Room 6115, Washington, DC 20590 5. Submitted By _

needed.

Date <u>2/2/06</u>